

CERTIFICATE OF COMPLIANCE

Certificate Number E513799
Report Reference E513799- A6002-UL
Issue Date 2020-APRIL-21

Issued to: POWERSOFT SPA
Via Conti 5
50018 Scandicci Fi ITALY

**This certificate confirms that
representative samples of**

COMPONENT - AUDIO/VIDEO, INFORMATION AND
COMMUNICATION TECHNOLOGY
EQUIPMENT

Audio Module Amplifier, IPALMOD

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety:

UL 62368-1, Audio/video, information and communication technology equipment Part 1: Safety requirements
CAN/CSA C22.2 No. 62368-1-14, Audio/video, information and communication technology equipment Part 1: Safety requirements


Additional Information:

See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

